

ABS Quality Evaluations

Certificate Of Conformance

This is to certify that the Environment Management System of:

Stelco Inc.

**2330 Haldimand Road 3
Nanticoke, ON N0A 1L0
Canada**

(WITH ADDITIONAL FACILITIES LISTED ON ATTACHED ANNEX)

has been assessed by ABS Quality Evaluations, Inc. and found to be in conformance with the requirements set forth by:


ISO 14001:2015

The Environment Management System is applicable to:


**COKE-MAKING, BY-PRODUCTS PLANT, IRONMAKING, STEELMAKING, LADLE METALLURGY, CONTINUOUS
CASTING, HOT STRIP MILL, WASTEWATER TREATMENT PLANT, CENTRAL POWER STATION, PLANT SERVICES,
MOBILE EQUIPMENT
REPAIR CENTER AND OTHER SUPPORT ACTIVITIES.**

This certificate may be found on the ABS QE Website (www.abs-qe.com). For certificates issued in the People's Republic of China information may also be verified on the CNCA website (www.cnca.gov.cn).

Certificate No: 60714
Original Certification Date: 14 March 2014
Effective Date: 13 March 2020
Expiration Date: 12 March 2023
Revision Date: 13 March 2020



Dominic Townsend, President



Validity of this certificate is based on the successful completion of the periodic surveillance audits of the management system defined by the above scope and is contingent upon prompt, written notification to ABS Quality Evaluations, Inc. of significant changes to the management system or components thereof.

ABS Quality Evaluations, Inc. 1701 City Plaza Drive, Spring, TX 77389, U.S.A.
Validity of this certificate may be confirmed at www.abs-qe.com/cert_validation.

ABS Quality Evaluations

ISO 14001:2015

Certificate Of Conformance

ANNEX

Certificate No: 60714

Stelco Inc.

At Below Facilities:

Facility: Pickle Lines #4 & #5
19 Hawk Street
Nanticoke, ON N0A 1L0
Canada

Activity: Pickling of steel coils

Facility: Pickle line #6
2070 Haldimand Road #3
Nanticoke, ON N0A 1L0
Canada

Activity: Pickling of steel coils.



Validity of this certificate may be confirmed at www.abs-qe.com/cert_validation.